

Fig. 1




Fig. 2




Fig. 3




Fig. 4






Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9

70




Fig. 10




Fig. 11




Fig. 12




Fig. 13






Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig . 19






Fig . 18



1 1 1 1





# Fig. 22




Fig. 23




Fig. 24






Fig. 25




Fig. 26




Fig. 27




Fig. 28




Fig. 29




Fig. 30




Fig. 31




Fig. 32







Fig. 33



1                  2                  3                  4

Fig. 35





Fig. 36



1 2 3 4




Fig. 38




Fig. 39




Fig . 40






Fig . 41




Fig. 42




Fig. 43




Fig. 44




Fig. 45




Fig. 46




Fig. 47




Fig. 48




Fig. 49




Fig. 50




Fig. 51




Fig. 52




Fig. 53






Fig. 54




Fig. 55




Fig. 56




Fig. 57





Fig. 58



**Fig. 59**

This technical drawing is an exploded perspective view of a mechanical assembly. The main components are shown in a disassembled state to illustrate their relative positions and assembly relationships. Key parts include a central housing (10) with a top flange (11) and a bottom flange (14). A central shaft (18) is shown passing through the housing, with a gear (14a) mounted on it. A cover (11) is shown at the top, and a base (14) is shown at the bottom. Various fasteners, including screws (32) and bolts (32a), are shown in their respective assembly positions. The drawing uses standard engineering conventions, with dashed lines indicating hidden internal features and arrows indicating the direction of assembly.




Fig. 60





Fig. 61






Fig. 62



Fig. 63




Fig. 64




Fig. 65




Fig. 66




Fig. 67





Fig. 68






Fig. 70






Fig. 71





Fig. 72



1 2 3 4




Fig. 74




Fig. 75




Fig. 76




Fig. 77




Fig. 78






Fig . 79




Fig . 80




Fig . 81




Fig . 82




Fig. 83




Fig. 84





Fig. 85






Fig. 86



Fig. 87




Fig. 88




Fig. 89





Fig. 90



4 3 2 1




Fig. 92




Fig. 93




Fig. 94






Fig. 95





Fig. 96



**Fig. 97**

Lens barrel  
advancing direction

- 11

- 32

11c

- 11e

— 11g

12a

12f

- 11b-Y

31

ED2

- 11g

11s-2

Lens barrel  
retracting direction

Fig. 98




Fig. 99




Fig. 100




Fig. 101




Fig. 102






Fig. 103




Fig. 104




Fig . 105





Fig. 106



2 3 4 5




Fig. 108






Fig. 110






Fig. 111





Fig. 112



34Y-c

Fig . 114




Fig . 115




Fig. 116





Fig . 117









Fig . 119






Fig . 121






Fig . 123




Fig . 124





Fig. 125



[illegible]



Fig . 127




Fig . 128





Fig . 129






Fig. 130

Fig. 131




Fig. 132




Fig. 133




Fig. 134






Fig. 135




Fig. 136




Fig. 137




Fig. 138




Fig. 139





Fig. 140






Fig. 142





Fig. 143






Fig. 144




Fig. 145




Fig. 146




Fig. 147




Fig. 148




Fig. 149




Fig. 150




Fig. 151




Fig. 152






Fig. 153




Fig. 154




Fig. 155

